

# Tolerance and Why $\pm 1/32$ " Matters

"Measure twice, cut once"

## What Is Tolerance?

Tolerance defines how far a part can deviate from its intended dimension while still working correctly.

Example:

- $10.000" \pm 1/32"$
- This means the part can be slightly larger or smaller and still be acceptable

## Why $\pm 1/32$ " Matters in FRC

A tolerance of  **$1/32$  inch (0.031")** may seem small, but in robotics it can:

- Prevent holes from lining up correctly
- Cause shafts or bearings to bind
- Create misalignment in drivetrains or elevators
- Stack into larger errors across assemblies

Small errors add up when multiple parts depend on each other.

## When Tight Tolerances Are Needed

Tight tolerances (like  $\pm 1/32$ ") are important when:

- Aligning bearing holes
- Mounting shafts or gears
- Building drivetrain frames
- Connecting pre-cut or CAD-matched parts

# When Loose Tolerances Are Acceptable

Looser tolerances are acceptable when:

- Mounting non-critical brackets
  - Creating sensor mounts with adjustment
  - Working with slots or oversized holes
  - Designing parts that need adjustability
- 

## Best Practice

- Measure twice before cutting or drilling
  - Use the same datum for all features
  - Center punch hole locations before drilling
  - Drill pilot holes before final sizing when precision is critical
- 

## Key Idea

Tolerance is not just a number—it is what determines whether parts fit together correctly or create assembly problems. In FRC,  $\pm 1/32$ " can be the difference between a smooth assembly and a misaligned mechanism.

---

Revision #2

Created 25 June 2026 18:24:23 by eharis

Updated 25 June 2026 18:37:45 by eharis